

19611954

Docket No.: 239870US2

ATTORNEYS AT LAW

COMMISSIONER FOR PATENTS ALEXANDRIA, VIRGINIA 22313

RE: Inventor: Mok-Kun JEONG, et al.

Patent No.: 6,913,574 B2_

Issued: July 5, 2005 Group Art Unit: 3737

Examiner: Francis J. JAWORSKI

For: METHOD AND APPARATUS FOR MEASURING

ELASTIC CHARACTERISTICS OF A MEDIUM BY USING ULTRASOUND IMAGES

Certificate
AUG 1 2 2005

of Correction

SIR:

Attached hereto for filing are the following papers:

REQUEST FOR CERTIFICATE OF CORRECTION CERTIFICATE OF CORRECTION FORM PTO 1050

Our check in the amount of \$0.00 is attached covering any required fees. In the event any variance exists between the amount enclosed and the Patent Office charges for filing the above-noted documents, including any fees required under 37 C.F.R 1.136 for any necessary Extension of Time to make the filing of the attached documents timely, please charge or credit the difference to our Deposit Account No. 15-0030. A duplicate copy of this sheet is enclosed.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND, MAIER & NEUSTADT, P.C.

/Marvin J. Spivak

Registration No. 24,913

Roland E. Martin

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 05/04)

22850

Customer Number

Registration No. 48,082

DOCKET NO.: 239870US2/smc



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: Mok-Kun JEONG, et al.

PATENT NO.: 6,913,574 62 GROUP: 3737

ISSUED: July 5, 2005 EXAMINER: Francis J. JAWORSKI

FOR: METHOD AND APPARATUS FOR MEASURING ELASTIC CHARACTERISTICS

OF A MEDIUM BY USING ULTRASOUND IMAGES

REQUEST FOR CERTIFICATE OF CORRECTION

DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE ALEXANDRIA, VA 22313-1450

SIR:

The following is a request for a Certificate of Correction in Serial Number 10/611,954, now Patent Number 6,913,574.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implement 35 USC 254, the Patent Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of the Patent Office, no fees are required. The requested corrections are listed on FORM P.T.O. 1050.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND, MAIER & NEUSTADT, P.C.

🕻 Marvin J. Spivak

Registration No. 24,913

Customer Number

22850

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 05/05) Roland E. Martin Registration No. 48,082 UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.:

6,913,574 B2

DATED:

Jul. 5, 2005

INVENTOR(S):

Jeong et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item (73), the Assignee information is incorrect. Item (73) should read:

-- (73) Assignee: Medison Co., Ltd., Hongchun-gun

(KR) --

Mailing address of sender:

Patent No.

6,913,574

Customer Number

22850

No. of add'l copies @ .30 per page

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 03/02)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.:

6,913,574 B2

DATED:

Jul. 5, 2005

INVENTOR(S):

Jeong et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item (73), the Assignee information is incorrect. Item (73) should read:

-- (73) Assignee: Medison Co., Ltd., Hongchun-gun

(KR) --

Mailing address of sender:

Patent No.

6,913,574

Customer Number

No. of add'l copies @ .30 per page

22850

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 03/02)